



Fatality Reports

Work-related fatality reports

Data source: CCOHS (Canadian Centre for Occupational Health and Safety)

Record Number: 265

CIS Descriptors: AGRICULTURAL EQUIPMENT
AGRICULTURE
FALLING OBJECTS

FATALITY REPORT

REPORT CHARACTERISTICS:

DONOR: Farm Safety Association, Inc.
JURISDICTION: Ontario
REPORT TITLE: Farm Fatality Report

INFORMATION ABOUT DECEASED:

NAME: Unavailable
OCCUPATION: Agriculture/Farming Operations
INDUSTRIAL SECTOR: Farming, Agriculture

ACCIDENT INFORMATION:

DATE OF FATALITY : 1982-10-23
PLACE OF ACCIDENT: Wellington County
BRIEF CAUSE OF DEATH: Unavailable.
BRIEF MANNER OF DEATH: Hydraulic lift dropped on the victim.
ACCIDENT DESCRIPTION:
Age of Deceased: Unknown

Day/Time of Accident: Saturday

Victim was repairing the front end hydraulic lift on tractor when the hydraulic pressure fluid line ruptured. The lift then dropped on the victim.

